

Friedemann Buschbeck ORGANBUILDING 416 Dunedin Circle Tampa, Florida 33617 Tel. 813 – 766 -5376 www.organbuilding.com



Repair of the R. Spurden Rutt Organ in Black River, Jamaica Saint John's Church



February 2021 Repairs done at the Rutt Organ

Swell keyboard keys regulated
Copple mechanic repair broken trackers, regulated
Cleaning of reservoir top
Examine of pedal windchest, need complete rebuilding
Repair of pedal keyboard with new felt
Packing of metal pipes from Swell Gedackt 8' and
Bordoun 16' for transport to Tampa, Florida
Repair weight for console door
Examen facade chest for front pipes, must be re-built
Tuning of the organ


Pedal coppler for Bass Flute 8'


Pedal pneumatic behind pedal board.





Pneumatic lines from swell to pedal pipes Bourdon 16





Pedal coppler with broken trackers, now repaired.

February 2021





Pipes on the great windchest

Deteriorated leather in pedal devision



BUSCHBECK ORGANBUILDING FRIEDEMANN BUSCHBECK www.organbuilding.com

